

測試報告

Test Report

嘉博貿易股份有限公司 INTERTRUST CORPORATION 台中市南屯區工業23路25號 NO. 25, 23 ROAD., INDUSTRIAL PARK, TAICHUNG 408, TAIWAN

以下測試樣品係由申請廠商所提供及確認 (The following sample(s) was/were submitted and identified by/on

behalf of the applicant as):

嘉博貿易股份有限公司 (INTERTRUST CORPORATION) 送樣廠商(Sample Submitted By) 樣品名稱(Sample Description) : PUFF DINO LONG-LASTING ANTI-RUST (恐龍長效防鏽劑)

號碼(No.): CE/2019/74624

樣品型號(Style/Item No.) DI74

收件日期(Sample Receiving Date) : 2019/07/24

2019/07/24 to 2019/07/30 測試期間(Testing Period)

測試需求(Test Requested) 依據客戶指定,於送測樣品中檢測鹵素-氟、氯、溴、碘含量. (As specified by

client, to test Halogen-Fluorine, Chlorine, Bromine, Iodine in the

日期(Date): 2019/07/30

頁數(Page): 1 of 4

submitted sample.)

測試方法(Test Method) : 請參閱下一頁 (Please refer to following pages).

測試結果(Test Results) 請參閱下一頁 (Please refer to following pages).







測試報告

Test Report

嘉博貿易股份有限公司

日期(Date): 2019/07/30

頁數(Page): 2 of 4

號碼(No.): CE/2019/74624

INTERTRUST CORPORATION 台中市南屯區工業23路25號 NO. 25, 23 ROAD., INDUSTRIAL PARK, TAICHUNG 408, TAIWAN

測試結果(Test Results)

測試部位(PART NAME) No.1 : 棕色液體 (BROWN LIQUID)

測試項目 (Test Items)	單位 (Unit)	測試方法 (Method)	MDL	結果 (Result) No.1
鹵素 / Halogen				
鹵素(氟)/ Halogen-Fluorine (F) (CAS No.: 14762-94-8)	mg/kg	參考BS EN 14582 (2016),以離子層析儀分析. / With reference to BS EN 14582 (2016). Analysis was performed by IC.	50	n. d.
鹵素(氯)/ Halogen-Chlorine (C1)(CAS No.: 22537-15-1)	mg/kg		50	n. d.
鹵素(溴)/ Halogen-Bromine (Br) (CAS No.: 10097-32-2)	mg/kg		50	n. d.
鹵素(碘)/ Halogen-Iodine(I) (CAS No.: 14362-44-8)	mg/kg		50	n. d.

備註(Note):

1. mg/kg = ppm; 0. 1wt% = 1000ppm

2. n.d. = Not Detected (未檢出)

3. MDL = Method Detection Limit (方法偵測極限值)




測試報告 **Test Report**

號碼(No.): CE/2019/74624 日期(Date): 2019/07/30 頁數(Page): 3 of 4

嘉博貿易股份有限公司 INTERTRUST CORPORATION 台中市南屯區工業23路25號 NO. 25, 23 ROAD., INDUSTRIAL PARK, TAICHUNG 408, TAIWAN

鹵素分析流程圖 / Analytical flow chart - Halogen

測試人員: 陳恩臻 / Technician: Rita Chen 測試負責人:張啟興 / Supervisor: Troy Chang





測試報告

Test Report

嘉博貿易股份有限公司 INTERTRUST CORPORATION 台中市南屯區工業23路25號 NO. 25, 23 ROAD., INDUSTRIAL PARK, TAICHUNG 408, TAIWAN

號碼(No.): CE/2019/74624

* 照片中如有箭頭標示,則表示為實際檢測之樣品/部位. * (The tested sample / part is marked by an arrow if it's shown on the photo.)

日期(Date): 2019/07/30

頁數(Page): 4 of 4

CE/2019/74624



** 報告結尾(End of Report) **